



**Fig. 1**

A block diagram showing a central **PROCESSOR** block. It is connected to four other blocks: **Battery**, **ACTIVATION BUTTON**, **ACCELEROMETER**, and **TRANSMITTER**. The **PROCESSOR** block is labeled with the number **20**. The **Battery** block is labeled with the number **24**. The **ACTIVATION BUTTON** block is labeled with the number **12**. The **ACCELEROMETER** block is labeled with the number **22**. The **TRANSMITTER** block is labeled with the number **26**.

10

Fig. 3



4 of 4

